

Heat Index	Risk Level	Protective Measures
Less than 91°F	<u>Lower</u>	Basic heat safety and planning
91°F to 103°F	<u>Moderate</u>	Implement precautions and heighten awareness
103°F to 115°F	<u>High</u>	Additional precautions to protect workers
Greater than 115°F	<u>Very High</u>	Triggers even more aggressive protective measures